



JAMES BURN INTERNATIONAL SAS

WIRE-O

LHERMITE

UNICOIL

67 rue du Docteur Blaizot, BP 134, 61304 L'Aigle Cedex, France  
www.wire-o.com www.jamesburn.com

DOCUMENT FINISHING SOLUTIONS

# TECHNICAL BULLETIN

N° ITM048

From : Joël HUET "Service engineer"  
Date : 26<sup>th</sup> November 2015

Number of Pages : 1  
(included this one)

**Application : Docupunch**

**- Retrofit: Docupunch with Plc : FX1S**

*SUBJECT : Replacement of the Plc FX1S-30MT-DSS from serial number 127*

As part as our ongoing effort to improve product quality, we have replaced the Plc FX1S-30MT-DSS part number JE29055 (End of life).

The new Plc FX3S-30MT-DSS (part number JE29093) can be fitted in place.

**Nota 1 : Important, specify us the old serial number, year and version.**

**Nota 2 : Before replacement check the PLC status :**

**1/ Check the PLC : If led Power «ON» or «OFF»**

**If led RUN «ON» or «OFF»**

**If led ERROR flashing «ON» or «OFF»**

**2/ Return to us the PLC if possible**